

PRINTER SETTINGS (1/3)

HL-1210W series Serial Number=U63982K3X872356
Main Controller Main ROM Version: 1.20
Engine Controller ROM Version: 1.06
RAM Size = 32Mbyte

Paper Tray	User Settings
Tray Size	:Letter

General Setup	User Settings
Local Language	:English
Ecology	
-Sleep Indication	:Dimmed
-Auto Power Off	:Off
-Toner Save	:Off
Interface	
-Auto IF Time	:5 Sec
-Input Buffer	:Level4
Replace Toner	:Stop


Print Menu	User Settings
Auto Continue	:On
Print Position	
-X Offset	:0 Dots
-Y Offset	:0 Dots

PRINTER SETTINGS (2/3)


L-1210W series Serial Number=U63982K3X872356
Main Controller Main ROM Version: 1.20
Engine Controller ROM Version: 1.06
RAM Size = 32Mbyte

Remaining life of :

Toner Cartridge



**Drum Unit



Device Status>

Total Page Count: 118

Total Pages Printed>

A4/Letter: 118

Legal/Folio: 0

B5/Executive: 0

A5: 0

Others: 0

Total Paper Jams: 1>

Jam Tray: 0

Jam Inside 1: 1

Jam Inside 2: 0

<Error History (last 10 errors)>

1: No Toner Page: 112

2: Jam Inside 1 Page: 4

3:

4:

5:

6:

7:

8:

9:

10:

<Replace Count>

Toner Cartridge: 0

Drum Unit: 0

<Toner Kind>

Inbox Toner

* Remaining life will vary depending on the types of documents printed,
their coverage and device usage.

** Based on A4/Letter printing.

PRINTER SETTINGS (3/3)

HL-1210W series Serial Number=U63982K3X872356

<<NETWORK CONFIGURATION>>

<Interface> WirelessLAN on
<Node Type> Brother NC-8400w, IEEE 802.11b/g/n (Active)
<Node Firmware Ver.> Firmware Ver.R (Apr 6 2023 09:52:12)
<MAC Address> 30-03-c8-54-8e-B3
<Node name> BRW3003C8548E83

<Active services> BRN3003C8548E83
 BINARY_P1
 TEXT_P1
 POSTSCRIPT_P1
 PCL_P1
 BRN3003C8548E83_AT

<Protocols>	Enabled	IPv6	Disabled
TCP/IP	Enabled	APIPA	Enabled
NetBIOS/IP	Enabled	SNMP	Enabled
WebBasedManagement	Enabled	Raw Port	Enabled
LPD	Enabled	WebServices	Enabled
IPP	Enabled	FTP	Enabled
SMTP	Enabled	mDNS	Enabled
TFTP	Enabled		
LLMNR	Enabled		

<IP Settings>
IP Address 0.0.0.0
Subnet Mask 0.0.0.0
IP Gateway 0.0.0.0
Boot Method AUTO
Boot Tries 3
IP Filter Disabled

GW Timeout (sec) 21
DNS Address Config AUTO
Primary DNS Server 200.48.225.130
Secondary DNS Server 200.48.225.146

<NetBIOS Name> BRW3003C8548E83
<WINS Address Config> AUTO
<Primary WINS Server> 0.0.0.0
<Secondary WINS Server> 0.0.0.0

<Send E-mail Settings(SMTP)>
Device Mail Address brn3003c8548e83@example.com
Server 0.0.0.0
Port 25

<mDNS Service Name> Brother HL-1210W series

<WebServices Name> Brother HL-1210W series [3003c8548e83]

<Comm. Mode> Infrastructure
<Name(SSID)> CUTIPA
<Authentication Mode> WPA/WPA2-PSK
<Encryption Mode> AES
<Wireless Link Status> Failed To Associate
<Tx Power Code> Full, 42, 0, 0

<Network Statistics>		<Wireless Statistics>	
Packets Received	626	RX Frames Received OK	0
Bytes Received	49767	RX Frames Error	4703
Packets Transmitted	0	TX Frames Transmitted OK	0
Bytes Transmitted	0	TX Frames Error	0

<Default Password> N50+5>AQ
Pwd: